

Release Notes IPC serie NEIUS

1099/562_V2

V26.0.12.20220303

File STEP1: TC-C35SS-I8Y-A_16M_O_V24.0.0.20220303_UKF.box (aggiornando con questo file la versione della Telecamera passa da **V24.2.0.20211026_SP2** a **V26.0.5.20220303**)

File STEP2: TC-C35SS-I8Y-A_16M_O_V26.0.12.20220303_UKF.box (aggiornando con questo file la versione della Telecamera passa da **V26.0.5.20220303** a **V26.0.12.20220303**)

ITALIAN

IMPORTANTE: se il dispositivo è connesso a Internet verificare la disponibilità di aggiornamenti tramite la sua pagina web: *Configurazione -> Impostazioni Sistema -> Manutenzione del Sistema -> Aggiornamento Sistema -> Aggiorna Cloud* e premere: *Test*. Se è disponibile una versione più recente procedere premendo *Aggiorna*. Alla fine di ogni aggiornamento verificare nuovamente la disponibilità di ulteriore nuovo firmware in Cloud.

IMPORTANTE: in caso di assenza di connettività Internet, procedere con l'aggiornamento locale tramite la stessa pagina web della telecamera oppure utilizzando il software *SearchConfig Tool V2.0* dopo aver scaricato il file di aggiornamento firmware dalla sezione **DOWNLOAD - FIRMWARE** del sito neius.urmet.com.

Per aggiornare, utilizzare i file nell'ordine indicato dagli STEP (file STEP1, file STEP2).

Modifiche STEP1 (V26.0.5.20220303):

1. Aggiunta opzione in pagina di Login per connessione sicura in HTTPS.
2. Corrette alcune traduzioni
3. Ottimizzazioni varie

Modifiche STEP2 (V26.0.12.20220303):

1. Corrette alcune modifiche legate al Roi, che causavano il riavvio dell'NVR.

ENGLISH

IMPORTANT: if the device is connected to the internet, check for updates via its webpage: *Configuration -> System -> Maintenance -> Upgrade -> Cloud Update* then press *Detecting*. If a more recent version is available press *Upgrade*. At the end of each upgrade, check again the availability of further new firmware in the Cloud.

IMPORTANT: if the device has no access to the Internet, download the update files from the DOWNLOAD - FIRMWARE section of the website neius.urmet.com, then proceed with the local update either via the usual webpage of the device or with the software *SearchConfig Tool V2.0*.

To update, use the files in the order indicated by the STEPs (STEP1 file, STEP2 file).

STEP1 Changes (V26.0.5.20220303):

1. Added option in Login page for secure HTTPS connection.
2. Fixed some translations
3. Various optimizations

STEP2 Changes (V26.0.12.20220303):

1. Fixed some ROI-related changes that caused the NVR to reboot.